



MOUNTING SCREW KIT CONSISTS OF 4 SCREWS AND NUTS,
METRIC THREAD ACCESSORY FOR: CIRCUIT BREAKER,
4 POLE 3VA2 100/160/250 AND FOR PLUG-IN UNITS
3VA2 100/160/250,
DRAW-OUT UNITS 3VA2 100/160/250

Similar to image

Further information:

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.com/lowvoltage/catalogs>

Global Industry Mall (Online ordering system)


<http://www.siemens.com/lowvoltage/mall>

Service&Support (Manuals, Certificates, Characteristics, FAQs,...)

<http://support.automation.siemens.com/WW/view/en/3VA9124-0SS10/all>

Image database (product images, 2D dimension drawings, 3D models, device circuit diagrams, ...)

http://www.automation.siemens.com/bilddb/cax_en.aspx?mlfb=3VA9124-0SS10



last change:

Apr 21, 2014